

Load Cell Wiring Colour Codes – from 1/1/2008 onwards

Load Cell	Mounting Assembly	Cable type	Excitation		Signal	
			+ve input	-ve input	+ve output	-ve output
T66*	AV, LeverMount® Lite	Blue PU	red	blue	green	yellow
350i	AV, LeverMount®	Blue PU	red	blue	green	yellow
350n	-	Black PVC	green	black	red	white
T20	LA20	Blue PU	red	blue	green	yellow
T21*	LA21	Blue PU	red	blue	green	yellow
T95	LA95	Blue PU	red	blue	green	yellow
VC3500	LA3500, MasterMount®	Blue PU	red	blue	green	yellow
T30	LA30	Yellow PVC	white	black	brown	blue
T34*	LA34, LA34 Silo	Blue PU	red	blue	green	yellow
650	-	Blue PU	red	blue	green	yellow
T60*	-	Blue PU	red	blue	green	yellow
T61	-	Blue PU	red	blue	green	yellow
T64	-	Blue PU	red	blue	green	yellow
T65*	-	Blue PU	red	blue	green	yellow
T16*	-	Blue PU	red	blue	green	yellow
Discontinued Load Cells						
350a	-	Black PVC	green	black	red	white
460	LA460	Black PVC	green	black	red	white
T90	LA90	Blue PU	red	blue	green	yellow
T93	LA93	Blue PU	red	blue	green	yellow
740	-	Blue PU	red	blue	green	yellow

* For load cells with 6-wire (sense) connections: +ve sense is **black** and -ve sense is **white**

Wiring Colour Codes for load cells supplied up to 31/12/2007

Load Cell	Mounting Assembly	Cable type	Excitation		Signal	
			+ve input	-ve input	+ve output	-ve output
T66	AV, LeverMount® Lite	Black PVC	green	black	red	white
350i	AV, LeverMount®	Black PVC	green	black	red	white
350a / 350n	-	Black PVC	green	black	red	white
T93	LA93	Blue PU	red	blue	green	yellow
T95	LA95	Blue PU	red	blue	green	yellow
460	LA460	Black PVC	green	black	red	white
VC3500	LA3500, MasterMount®	Blue PU	red	blue	green	yellow
T30	LA30	Yellow PVC	white	black	brown	blue
T61	-	Blue PU	red	blue	green	yellow
T90	LA90	Blue PU	red	blue	green	yellow
650	-	Black PVC	green	black	red	white
740	-	Black PVC	green	black	red	white